



- Building from outside - corner of kitchen has been subjected to infestation by bees (possibly carpenter bees).
- Roof damage on other side & water rain destroyed the ceiling.



ceiling in other bedroom



ceiling in one bedroom



Image of solar panels & camper (2024)

The stolen panels cut the electric power completely, causing sump pump failure.

(Previous failure due to rain shutdown the Electricity from the grid since the breaker system was flooded.)



Image of solar panels structure and (camper missing)
after the robbery.