

**MOLD STARTS AT THE FAN AND  
MOVES TOWARDS THE GABLE VENT  
AT RIGHT END OF HOUSE.**





The image shows the interior of an attic with a gable roof. The wooden rafters and joists are visible, along with a gable vent that appears to be mostly blocked. The text overlay indicates that moisture is migrating from the attic towards the vent.

**ATTIC MOISTURE IS MIGRATING TO  
GABLE VENT THAT IS MOSTLY  
BLOCKED**

1:22



Geneva  
January 28 6:08 PM

Edit



LIVE



1:22





Geneva  
January 28 6:08 PM

Edit



LIVE



1:22



Geneva  
January 28 6:08 PM

Edit

LIVE

