


moet peker den eye  
eil over hoo



Wood pecker damage  
(also ~~damaged~~  
became a  
Carolina wren nest)

Wood pecker damage  
all over house



H<sub>2</sub>O at  
front  
door  
entrance

A photograph of a stone step in a garden or courtyard. The step is a large, rectangular, light-colored stone. On the step, there is handwritten text in black ink that reads "A20 at front entrance". The step is surrounded by other stones, some of which are smaller and more irregular. There is a large puddle of water on the ground to the left of the step, reflecting the sky and the surrounding environment. The ground is covered with fallen leaves, twigs, and some small plants. The overall scene is outdoors and appears to be a well-maintained garden area.

A20  
at front  
entrance



H2O at front  
entrance



1120  
45 inches  
deep at front  
door



Hed  
front  
door



water frozen



H<sub>2</sub>O on Property





H<sub>2</sub>O  
on  
property



H2O  
on  
property






bathroom ceiling  
leak  
now fixed

cabinet fell off  
wall, new  
cabinet  
installed


gap  
at  
shower



barn  
ceiling

A hand-drawn arrow in black ink, pointing upwards and to the right, positioned between the words 'barn' and 'ceiling'.

1 opening to  
get in  
basement  
crawl  
space

A photograph of a cramped, dark basement space. The ceiling consists of horizontal wooden joists. A single, small, glowing light source is visible in the distance, casting a beam of light across the scene. The floor is dirt and appears cluttered with various items, including what looks like a fan on the right side. Handwritten text is visible on a wooden board in the foreground.

1/2 basement space  
dirt to top

have to belly walk to  
get in there

dirt  
1/2 base mat

2nd  
opening  
then  
crawl to  
5' of  
dirt





stick  
holding  
up  
kitchen  
cabinet



counter top

getting pushed  
together





drips down  
from  
creature  
living in  
soffit  
outside

see next page

dirty soffit  
along entire  
front of house

Something lived up there

I have been  
trapping




backhouse  
door

Winter  
bucket  
collection  
H<sub>2</sub>O in  
Doot house



booth house  
broken window (2)





back deck  
broken  
10' fall



Clear  
12/22/19